

Part 573 Safety Recall Report

18V-438

Manufacturer Name : Newmar Corporation**Submission Date :** JUN 28, 2018**NHTSA Recall No. :** 18V-438**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 930

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Newmar Bay Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2018-2018 Newmar King Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2018-2018 Newmar London Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.
Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2018-2018 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.
Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2018-2018 Newmar Bay Star Sport

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.
Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2018-2018 Newmar Canyon Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 7 : 2018-2018 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 8 : 2018-2018 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 9 : 2018-2018 Newmar New Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.

Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 10 : 2018-2018 Newmar Ventana LE
Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
Body Style :
Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.
Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Vehicle 11 : 2018-2018 Newmar Ventana
Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
Body Style :
Power Train : NR

Descriptive Information : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property.
Correction: Dealers will replace the slide-out controller. Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Production Dates : JAN 08, 2018 - JUN 01, 2018

VIN Range 1 : Begin : NR **End :** NR Not sequential

Description of Defect :

Description of the Defect : after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning.
This could increase the risk of injury and/or damage to property.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : On certain motorhomes, after the battery disconnect is turned on, the controller for the slide-out rooms could cause the slide-outs to move in or out unexpectedly without warning. This could increase the risk of injury and/or damage to property. Correction: Dealers will replace the slide-out controller.
Note: This condition can only happen with the ignition key in the off/accessory position and the battery disconnect on.

Description of the Cause : Bad slide-out controller

Identification of Any Warning that can Occur : N/A

Supplier Identification :**Component Manufacturer**

Name : Newmar Corporation
Address : 355 N Delaware St.
Nappanee INDIANA 46550
Country : United States

Chronology :

On 6/18/2018 Engineering was made aware of a potential defect. On 6/25/2018 a decision was made to file a safety recall. On 6/28/2018 Newmar is filing a safety recall.

Description of Remedy :

Description of Remedy Program : Dealers will replace the slide-out controller at no cost to the customer.
How Remedy Component Differs from Recalled Component : NR
Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 08/27/2018 customer/dealer letters will be mailed out.
Planned Dealer Notification Date : AUG 27, 2018 - AUG 27, 2018
Planned Owner Notification Date : AUG 27, 2018 - AUG 27, 2018

* NR - Not Reported