18V-745

Part 573 Safety Recall Report

Manufacturer Name :Altec Industries Inc.Submission Date :0CT 22, 2018NHTSA Recall No. :18V-745Manufacturer Recall No. :CSN 700

Manufacturer Information :

Manufacturer Name : Altec Industries Inc. Address : 210 Inverness Center Drive

Birmingham AL 35242 Company phone : 205-991-7733

Vehicle Information :

Vehicle 1:2014-2018 Altec : DHH and DHB Digger DerricksVehicle Type :Body Style :Body Style :Image: Derrick State State

Population:

Description of Defect :

Description of the Defect : FMVSS 1 :	The software on the Zone Rating System module may be incorrect. NR
FMVSS 2 :	NR
Description of the Safety Risk :	The Zone Rating System may not alert the operator that the load being handled exceeded the rated load for the specific unit position. This could lead to a greater risk of unit instability or loss of load control increasing the risk of death or serious injury.
Description of the Cause :	NR
	The Zone Rating System is an operator aid and is not the primary means of determining the capacity limits of the unit.

Supplier Identification :

Component Manufacturer

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 175 Estimated percentage with defect : 10 %

Part 573 Safety Recall Report18V-745			
Name : NR Address : NR NR Country : NR			
Chronology : In August 2018 during a unit final in Zone Rating System, did not match th pre-programmed software modules unable to overwrite the existing unit the information to be incorrect. There have been no reports of accide	he physical machine. Altec's inv were being re-programmed and information that is stored in th	estigation of the issue has determind used. The re-programming proces	ned that ss is
Description of Remedy : Description of Remedy Program :	will inform the customer 1) th	customers of the affected units. Th at the derrick can continue to be us rts, and 2) update the Zone Rating S	ed
		les will have the correct unit inform racy and the performance of the Zo design intent	
Identify How/When Recall Condition was Corrected in Production :	0	and retraining. The pre-programme	
Recall Schedule :			
Description of Recall Schedule :	will inform the customer 1) that	customers of the affected units. Th at the derrick can continue to be us rts, and 2) update the Zone Rating S	ed
Planned Dealer Notification Date : Planned Owner Notification Date :			

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR $\S573$