# Part 573 Safety Recall Report

Manufacturer Name :Heartland Recreational Vehicles, LLCSubmission Date :0CT 29, 2018NHTSA Recall No. :18V-760Manufacturer Recall No. :99.01.41

## Manufacturer Information :

Manufacturer Name :Heartland Recreational Vehicles, LLCAddress :1001 All Pro DriveElkhart IN 465148772628032

#### **Population :**

Number of potentially involved : 368 Estimated percentage with defect : 100 %

云 🔨 🕰

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

18V-760

## Vehicle Information :

Vehicle 1:	2019-2	2019 Heartland Pioneer	BH280			
Vehicle Type :	TRAIL	ERS				
Body Style :						
Power Train :	NR					
Descriptive Information :		A flexible LP gas line was installed on the outside cooktop running into the firebox of the stove. Installation instructions states this must be rigid metal or copper.				
Production Dates :	MAR 1	7, 2017 - OCT 10, 2018				
VIN Range 1:	Begin :	5SFPB3427JE350491	End :	5SFPB3428KE406939	✓ Not sequential	

### **Description of Defect :**

Description of the Defect :	A flexible LP gas line was installed on the outside cooktop running into the firebox of the stove. Installation instructions states this must be rigid metal or copper.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	The flexible hose can be damaged and increase the risk of fire and or physical injury.
Description of the Cause :	Incorrect installation of the stove per manufactures installation instructions.
Identification of Any Warning that can Occur :	Visual damage to the flexible LP hose if it was inspected.

### **Supplier Identification :**

#### **Component Manufacturer**

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Re	call Report	18V-760	Page 2
Name : NR			
Address : NR			
NR			
Country: NR			
Chronology :			_
10/11/18 during a plant audit it was discussion it was brought up that the			
stove. After review of the installation			
10/12/18 discussion was take to pu	rchasing to determine what was	s affected and the range of potentia	ally affect
units. 10/15/18 the information was meeting was called and the issue wa			
concern and that a recall should be i			icty
Description of Remedy :			
Description of Remedy Program :	To replace the Flexible LP hose a rigid metal line.	e inside the Firebox of the outside s	stove with
How Remedy Component Differs from Recalled Component :	The replacement component w	ould be Rigid metal.	
Identify How/When Recall Condition was Corrected in Production :	10/3/18 the production line di inside the firebox and replaced		iose
	•		
Recall Schedule :			
Description of Recall Schedule :	Notices will begain once the dra	aft letter is approved.	
Planned Dealer Notification Date :			
Planned Owner Notification Date :	DEC 21, 2018 - DEC 21, 2018		

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573