

Part 573 Safety Recall Report

18V-936

Manufacturer Name : Arcimoto Inc
Submission Date : MAR 29, 2019
NHTSA Recall No. : 18V-936
Manufacturer Recall No. : 7F7-X7F9K-12

**Manufacturer Information :**

Manufacturer Name : Arcimoto Inc
Address : 2034 W. 2nd Ave
 Eugene OR 97402
Company phone : 5958232

Population :

Number of potentially involved : 22
Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2018 Arcimoto FUV
Vehicle Type : MOTORCYCLES
Body Style : OTHER
Power Train : HYBRID ELECTRIC

Descriptive Information : The recall population was determined by inspection. The affected vehicles did not have a certification label as required by 49 CFR Section 567.4.

Production Dates : NOV 01, 2017 - DEC 21, 2018

VIN Range 1 : Begin :	7F7ATR317HEB00000	End :	7F7ATR317HEB00001	<input type="checkbox"/> Not sequential
VIN Range 2 : Begin :	7F7ATR319JEB00001	End :	7F7ATR315JEB00003	<input type="checkbox"/> Not sequential
VIN Range 3 : Begin :	7F7ATR317JEB00020	End :	7F7ATR317JEB00018	<input type="checkbox"/> Not sequential
VIN Range 4 : Begin :	7F7ATR319JEB00005	End :	7F7ATR319JEB00005	<input type="checkbox"/> Not sequential
VIN Range 5 : Begin :	7F7ATR312JEB00007	End :	7F7ATR317JEB00018	<input type="checkbox"/> Not sequential
VIN Range 6 : Begin :	7F7ATR315JEB00020	End :	7F7ATR310JEB00023	<input type="checkbox"/> Not sequential
VIN Range 7 : Begin :	7F7ATR315JEB00020	End :	7F7ATR310JEB00023	<input type="checkbox"/> Not sequential

Description of Noncompliance :

Description of the Noncompliance : These vehicles did not have a certification label as required by 49 CFR Section 567.4

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : Not applicable.

Description of the Cause : Unawareness of the requirements under 49 CFR Section 567.4.

Identification of Any Warning that can Occur : Not applicable.

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

During the investigation of a non-related non-compliance recall, it was discovered that the vehicle did not have a certification label as required by 49 CFR Section 567.4. This issue was discussed with the Review Board on 12/18/2018, who escalated this to the PCM Group. The PCM Group met on 12/20/2018 and decided to escalate this as a recall candidate. Senior Management approved the recall on 12/21/2018.

Description of Remedy :

Description of Remedy Program : The non-compliance will be remedied by affixing the required label in the required location indicating compliance with FMVSS requirements and providing the information required by Part 567. This will be done free of charge to purchasers and owners. To the best of our knowledge, no owners have incurred any costs resulting from this non-compliance.

How Remedy Component Differs from Recalled Component : Not applicable.

Identify How/When Recall Condition was Corrected in Production : Before production resumes, a label compliant to Part 567 will be added to the Bill Of Materials and the Assembly Instructions.

Recall Schedule :

Description of Recall Schedule : Arcimoto has retrieved all vehicles subject to this recall. All vehicles are currently under Arcimoto control and will not be returned to their owners or used on public roads until all recalls have been completed by Arcimoto.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported