OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-936

Manufacturer Name: Arcimoto Inc Submission Date: OCT 30, 2019 NHTSA Recall No.: 18V-936 Manufacturer Recall No.: 7F7-X7F9K-12



Manufacturer Information:

Manufacturer Name: Arcimoto Inc

Address: 2034 W. 2nd Ave

Eugene OR 97402

Company phone: 5958232

Population:

Number of potentially involved: 23 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2017-2018 Arcimoto FUV

Vehicle Type: MOTORCYCLES

Body Style: OTHER

Power Train: HYBRID ELECTRIC

Descriptive Information: The recall population was determined by inspection. The affected vehicles did not

have a certification label as required by 49 CFR Section 567.4.

Production Dates: NOV 01, 2017 - DEC 21, 2018

Description of Noncompliance:

Description of the These vehicles did not have a certification label as required by 49 CFR Section

Noncompliance: 567.4

FMVSS 1: 567 - Certification

FMVSS 2: NR

Description of the Safety Risk: Not applicable.

Description of the Cause: Unawareness of the requirements under 49 CFR Section 567.4.

Identification of Any Warning Not applicable.

that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

During the investigation of a non-related non-compliance recall, it was discovered that the vehicle did not have a certification label as required by 49 CFR Section 567.4. This issue was discussed with the Review Board on 12/18/2018, who escalated this to the PCM Group. The PCM Group met on 12/20/2018 and decided to escalate this as a recall candidate. Senior Management approved the recall on 12/21/2018.

Description of Remedy:

Description of Remedy Program: The non-compliance will be remedied by replacing the subject vehicle with

a fully compliant vehicle, including an affixed certification label in the required location indicating compliance with FMVSS requirements and providing the information required by Part 567. This will be done free of charge to purchasers and owners. To the best of our knowledge, no

owners have incurred any costs resulting from this non-compliance.

How Remedy Component Differs Not applicable.

from Recalled Component:

Identify How/When Recall Condition Before production resumes, a label compliant to Part 567 will be added to

was Corrected in Production: the Bill Of Materials and the Assembly Instructions.

Recall Schedule:

Description of Recall Schedule: Arcimoto has retrieved all vehicles subject to this recall. All vehicles are

currently under Arcimoto control and will not be returned to their owners or used on public roads until all recalls have been completed by

Arcimoto.

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

* NR - Not Reported