

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	12	07	2018	<b>Expires on</b>	01	07	2019
----------------	----	----	------	-------------------	----	----	------

<b>From</b>	Parts Operations
-------------	------------------

<b>Subject</b>	Part Number Changes for Takata Airbag Inflator Safety Recall Bulletins
----------------	--

Effective December 7th, 2018, all of the current Passenger Airbag Inflator bulletins will be revised to add new kit part numbers. This is a result of Takata's bankruptcy and a change to the purchasing flow.

There are no changes to specification, form, fit, function, or cost. Takata's bankruptcy will not affect our supply of replacement inflators required to complete recall repairs; all of our inflators are sourced from other companies.

You may receive different inflator part numbers than what you ordered. Make sure you review the most **recent version of the service bulletins available on SIS** for installation instructions, warranty information, and which part numbers your dealership may receive.

The following bulletins are affected by these new parts:

<u>Honda</u>	<u>Acura</u>
A15-067	B15-049
A16-047	B16-028
A16-048	B16-029
A17-001	B17-001
A17-002	B17-002
A17-024	B18-002
A18-002	B18-003
A18-003	B18-054
A18-098	B18-055
A18-099	

Always check SIS to make sure you have the most current version of the **bulletin available**. Make sure you do a VIN status inquiry on every vehicle that arrives on your service drive to determine if any outstanding safety recall or other campaign repairs apply.

Thank you,

American Honda Motor Company

MD/ms