

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4817
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 08, 2018

Subject: 18159 03 – Noncompliance Recall
Fuel Leak During F/CMVSS Testing
Revised Service Procedure

Models: 2016-2018 Chevrolet Cruze LS Gasoline-Engine Vehicles
with Tire Inflator Kit (RPO KTI)

To: All General Motors Dealers

This bulletin is being revised to update the Service Procedure section. An additional graphic and instructions not to install a fuel line secondary latch if it is not present has been added. Please discard all previous copies of bulletin 18159.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS