

Cruise Control Software UpgradeBy **Mopar** on Thursday, July 19, 2018

CRUISE CONTROL SOFTWARE UPGRADE

"LOSS OF COMMUNICATION" ERROR



Mopar has received feedback from dealers experiencing "loss of communication" while performing Cruise Control Campaigns: **U49, U59, U60, U61, U62, U63, U64, U65, U66 and U73**. Mopar has also seen an increase in requests for replacement batteries under warranty.

In an effort to reduce warranty expense and minimize communication error(s) during repair, please review dealer instructions for each campaign with service teams. Step 1 of instructions explains vehicle first needs installation of battery charger to verify charging rate is within specifications. Insufficient battery rates can result in unsuccessful flashes. Click **HERE** to view instructions.

Thank you for your support.