

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4771
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 5, 2018

Subject: 18179 01 – Safety Recall
SDM Loss of Communication
Revised Service Procedure and Warranty Information

Models: 2018 GMC Terrain

To: All General Motors Dealers

This bulletin is being updated to add additional information to the service procedure. Before programming the SDM verify that the “service airbag” light is not illuminated. If the “service airbag” light is illuminated, check for the presence of DTC U0151. If DTC U0151 is currently stored, remove the SDM fuse (located in the instrument panel fuse block) for a period of 30 seconds or more. Once the fuse is reinstalled, verify that DTC U0151 is cleared and proceed with reprogramming the SDM. Please discard all previous copies of bulletin 18179.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS