

Federal Recall Information

18KWD / 18V368 / 2018-389

Supplier

Kenworth

Description

The Tractor ABS lamp may not illuminate when the vehicle experiences a loss of battery and/or ignition power to the ABS controller. Unknowingly operating a vehicle with an inoperative ABS system could lead to an increased risk of an accident or injury.

Release Date

7/16/2018

Introduction

Kenworth Truck Company has determined that certain Vehicle Model Year 2007 through 2019 C500, T440/T470, T600, T660, T680, T800, T880, and W900 vehicles manufactured from January 24, 2007 through January 31, 2018 fail to conform to the following standards:

- U.S. Federal Motor Vehicle Safety Standard (FMVSS) No. 121 - Air brake systems;
- FMVSS No. 136 - Electronic Stability Control Systems on Heavy Vehicles;
- Canada Motor Vehicle Safety Standard (CMVSS) No. 121 - Air brake systems; and
- CMVSS 136 - Electronic Stability Control Systems on Heavy Vehicles.

Fleets may have vehicles included in this recall and in Safety Recall [20KWB](#).

Revision Notes

- 04/17/2020: Updated chassis list, Introduction, and Situation.
- 08/08/2018: Phase 1 Chassis List and Interim Customer Notification letters have been attached.

Situation

40,685 chassis (40,590 U.S. and 95 Canada) C500, T440/T470, T600, T660, T680, T800, T880, and W900 built from 01/24/2007 through 01/31/2018 equipped with:

- NAMUX3 with software version P30-1031-1001 through -120
- NAMUX4 with software version P30-1011-003 through -143

Resolution

This bulletin will be updated as a repair procedure is completed and made available.

This bulletin will also be updated as more chassis that require this repair are identified.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Attachments

 [Dealer\Chassis List](#)

 [U.S. Interim Customer Letter](#)

 [Canada Interim Customer Letter](#)

Authored by: OF