

Tractor ABS Lamp

Author:

6/18/2019

Title	18KWD: Tractor ABS Lamp
Search Words	
Bulletin No.	18KWD
What's New Abstract	Safety Recall - The Tractor ABS Lamp may not illuminate when vehicle experiences a loss of battery and/or ignition power to the ABS controller. This may allow the operation of the vehicle without a functional tractor ABS system.
Supplier	Kenworth
Description	The Tractor ABS lamp may not illuminate when the vehicle experiences a loss of battery and/or ignition power to the ABS controller. Unknowingly operating a vehicle with an inoperative ABS system could lead to an increased risk of an accident or injury.
Release Date	
Introduction	Kenworth Truck Company has determined that a defect, which relates to motor vehicle safety, exists in certain T660, T680, T800, T880, and W900 chassis manufactured between May 21, 2014 and December 17, 2017.
Situation	
Resolution	This bulletin will be updated as soon as a chassis list and a repair procedure is completed and made available.
It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.	
Warranty	
Parts	
Labor	
Procedure	

Shipping	
Freight	
Contact	
Attachments	