

# Federal Recall Information

---

**18PBB**

## What's New

Safety Recall - The Tractor ABS Lamp May Not Illuminate When ABS Controller Loses Battery and/or Ignition Power

---

## Supplier

Peterbilt

---

## Description

The Tractor ABS Lamp May Not Illuminate When ABS Controller Loses Battery and/or Ignition Power

---

## Release Date

7/16/2018

---

## Introduction

Peterbilt Motors Company has decided that certain Model Year 2015, 2016, 2017, and 2018 vehicle Models 365, 367, 384, 386, 389, 567, and 579 manufactured between June 13, 2014 and December 18, 2017 fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) No. 121 - Air brake systems and 136 - Electronic Stability Control Systems on Heavy Vehicles.

If the ABS controller loses battery and /or ignition power the ABS system becomes inoperative, in some configurations, the ABS warning lamp on the dash does not illuminate. Unknowingly operating a vehicle with an inoperative ABS system could lead to an increased risk of an accident.

---

## Resolution

This bulletin will be updated as soon as an affected chassis list is defined and a repair procedure is developed.

---

**It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.**

---

## **Parts**

No parts required, software only

---