

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions
about this Letter, please
submit your inquiry on the
Web using the [WSC Link](#)
on DTNACconnect

REF #: ICI19-033

Effective: 07/8/19

Release: 07/8/19

SUBJECT: FL780B – Campaign Reactivated and Revised - Group B

This letter is to inform you that recall FL780, Cascadia ICUC Bulb Check Function - Group B, was reactivated today, Monday 7/8/19. You will now see the FL780B active in OWL.

A revised bulletin for FL780AB Cascadia ICUC Bulb Check Function is available on DTNACconnect. Please print and use the revised bulletin for all work under FL780 from this point forward.

REVISIONS: Part number BW200 0229N - Tire Pressure Monitoring System (TPMS) ECU, required for Group B, has been added to the parts table and is now available for ordering. Work instructions for replacement of the TPMS have been added to the bulletin.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNACconnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.