

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions
about this Letter, please
submit your inquiry on the
Web using the [WSC Link](#)
on DTNAConnect

REF #: ICI19-060

Effective: 10/31/19

Release: 10/31/19

SUBJECT: FL780 – Fourth Revised Bulletin

This letter is to inform you that a revised bulletin for Recall FL780 Cascadia ICUC Bulb Check Function – is available on DTNAConnect. Please print and use the revised bulletin for all work under FL780 from this point forward.

REVISION: Group B TPMS replacement instructions have been added back in (Steps 28-39). The work instructions have been revised for improved clarity of individual programming steps to ensure that the vehicle parameters are uploaded to the server correctly.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.