

PARTS BULLETIN

Subject: Recall R39901:XC60 T8 CHARGE CORD	Group: 37	No: R39901
MY 2019 XC60 T8	Market: US	
	Date: 9/5/18	

Reference Bulletin: QB R39901

Volvo Car USA LLC (Volvo) on behalf of Volvo Car Group, has decided to launch Recall R39901 on a **limited** number of model year 2019 XC60 T8 vehicles.

Volvo has identified that the charge cord may have been manufactured with an incorrect capacitor that could pose a risk of a thermal event and/or present a shock hazard.

The corrective action is to inspect the charge cord serial number and compare it to the R39901 Concerned Serial Number list in TIE, per the attached instructions and replace it if necessary.

IMPORTANT

Do not use the charge cord on any vehicle eligible for this recall until it is inspected.

Volvo Customer Care will contact vehicle owners directly and will assist in making service appointments with the selling retailer. Vehicle owners will need to bring the charge cord with them when visiting the retailer for this recall.

All replaced charge cords will need to be returned to the Technical Material Analysis department.

A total of 35 U.S. vehicles are eligible for this recall.

The following part number applies:

Part Number	Description	Qty
31419235	Charge Cord (harness)	1