

T680/T880/W990 Side Extender Intermediate Marker Lamp Reflector

Author:

6/18/2019

Title	18KWF: T680/T880/W990 Side Extender Intermediate Marker Lamp Reflector
Search Words	
Bulletin No.	18KWF
What's New Abstract	Safety Recall – Interim Notification – Certain 2.1m vehicles equipped with side extender mounted intermediate marker lamp/turn signals do not meet FMVSS 108 requirements for intermediate side marker lamps and reflex reflectors for vehicles 30 ft. and greater overall length. Failure to adequately warn surrounding or oncoming motorists of vehicle presence during conditions of reduced visibility may increase the risk of a crash.
Supplier	Kenworth Truck Company
Description	T680, T880, and W990 vehicles equal to or greater than 30 feet long require a reflex reflector.
Release Date	
Introduction	Kenworth Truck Company has determined that a defect, which relates to motor vehicle safety, exists in certain T680, T880, and W990 chassis manufactured from December 10, 2012 through October 10, 2018 fail to conform to Federal Motor Vehicle Safety Standard (FMVSS/CMVSS) No. 108 - Table 1-a requirements, which require an intermediate side marker lamp and reflex reflector. Failure to adequately warn surrounding or oncoming motorists of vehicle presence during conditions of reduced visibility may increase the risk of a crash.
Situation	1627 chassis (1555 U.S. and 72 Canada) T680, T880, and W990 built from 12/10/2012 through 10/10/2018 equipped with an extender mounted intermediate marker lamp/turn signal.
Resolution	This bulletin will be updated as soon as parts are available.
It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.	

Warranty	
Parts	
Labor	
Procedure	
Shipping	
Freight	
Contact	
Attachments	