

MERCEDES-BENZ USA, LLC One Mercedes-Benz Dr. Sandy Springs, GA, 30328 Phone: (770) 705-0600 Fax: (770) 705-0117 MBUSA.com

## newschannel update

TO: Mercedes-Benz Dealer Principals, General	FROM: Gregory Gunther, Department Manager,	
Managers, Sales Managers, Service Managers, Parts	Vehicle Compliance and Analysis, Engineering	
Managers	Services	
RE: Recall Campaign Initial Notification		
Check Headlight Screw, Rework if Necessary	DATE: January 4, 2019	
MY19 257 (CLS-Class)	DATE. January 4, 2019	

## **IMPORTANT NEW RECALL CAMPAIGN INFORMATION**



ble on the <u>www.safercar.gov</u> web will be flagged in VMI as "PENDIN <b>Backgrou</b> Daimler AG ("DAG"), the main certain CLS-Class vehicles accessible which does not main to meet this requirement by removable sealing cap after Mercedes-Benz dealer will of	anufacturer of Mercedes-Benz vehicles, has determined that on (257 platform), the horizontal adjustment mechanism might be eet the requirements of FMVSS 108. Subject vehicles are designed sealing off the headlamp horizontal adjustment screw with a non-	
ble on the <u>www.safercar.gov</u> web will be flagged in VMI as "PENDIN <b>Backgrou</b> Daimler AG ("DAG"), the main certain CLS-Class vehicles accessible which does not main to meet this requirement by removable sealing cap after Mercedes-Benz dealer will of	bsite and may generate questions from customers. Affected VINs NG" on January 4, 2019. Ind anufacturer of Mercedes-Benz vehicles, has determined that on (257 platform), the horizontal adjustment mechanism might be leet the requirements of FMVSS 108. Subject vehicles are designed sealing off the headlamp horizontal adjustment screw with a non-	
Backgrou Daimler AG ("DAG"), the micertain CLS-Class vehicles accessible which does not mic to meet this requirement by removable sealing cap afte Mercedes-Benz dealer will of	anufacturer of Mercedes-Benz vehicles, has determined that on (257 platform), the horizontal adjustment mechanism might be eet the requirements of FMVSS 108. Subject vehicles are designed sealing off the headlamp horizontal adjustment screw with a non-	
certain CLS-Class vehicles accessible which does not m to meet this requirement by removable sealing cap afte Mercedes-Benz dealer will c	(257 platform), the horizontal adjustment mechanism might be eet the requirements of FMVSS 108. Subject vehicles are designed sealing off the headlamp horizontal adjustment screw with a non-	
	Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain CLS-Class vehicles (257 platform), the horizontal adjustment mechanism might be accessible which does not meet the requirements of FMVSS 108. Subject vehicles are designed to meet this requirement by sealing off the headlamp horizontal adjustment screw with a non- removable sealing cap after initial adjustment in the manufacturing plant. An authorized Mercedes-Benz dealer will check the horizontal headlight adjusting screws on the affected vehicles and seal them, if necessary	
MBUSA will conduct a voluntary recall. <b>An additional notification will be sent when the remedy is available.</b>		
	Parts are currently unavailable. An additional notification will be sent once the parts are available for repairs.	
Vehicles Aff	fected	
2019		
CLS-Class		
Vehicle Popu	Ilations	
104		
43		
vehicle has been repaired. Or available in Star TekInfo Onco vehicles may continue to be	r lease any <u>new</u> MY19 CLS-Class vehicles in dealer inventory nce the remedy is available, the vehicles will be flagged as e the repair is complete, the vehicle may be sold or leased. driven, but must not be retailed until repaired. <u>car rental companies</u> to rent new MY19 CLS-Class vehicles e vehicle has been repaired.	
Next Steps/	/Notes	
Customer letters will be m available.	nailed approximately one week after the remedy becomes	
AOMs – This recall may ge your dealers ASAP.	enerate questions from your dealers. Please forward this notice to	
representative for further	cles in your fleet. Please contact your respective MBUSA fleet information and next steps. For repairs, please contact your	
	available.   AOMs – This recall may ge   your dealers ASAP.   This recall may affect vehic	