



IMPORTANT SAFETY RECALL

This notice applies to your vehicle
Recall Campaign: 18V321 – Brake Pedal Clevis Pin Clip
Subject: 2017-2018 Slingshot / SL / SLR / GT
Brake Pedal Clevis Pin Clip Inspection / Installation
PLEASE READ IMMEDIATELY

VIN T-18-02

FIRST NAME LAST NAME
ADDRESS
CITY, ST ZIP

Dear Slingshot Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Slingshot Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some 2017-2018 Slingshot vehicles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

A small number of Slingshot vehicles may have been manufactured with a brake pedal clevis pin clip that was not installed properly. A misassembled or absent clevis pin clip may allow the clevis pin to back out of the assembly thereby causing a loss of brake ability and increasing the risk of a crash.

What Polaris and your dealer will do:

Inspect and install (if necessary) your brake pedal clevis pin and clip. Your Polaris Slingshot dealer has been authorized to complete the brake pedal clevis pin clip inspection and installation (if necessary) at no cost to you.

What you should do:

Please contact your local Slingshot dealer at your earliest convenience to schedule an appointment to have bulletin repairs performed. The inspection and repair (if needed) may take approximately 15 minutes. When making contact with your dealer, discuss their schedule and how long they will need to keep your vehicle to complete the updates.

If you have questions or if you need more information:

While your Slingshot dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, if you are having difficulty obtaining the recall repairs outlined in this letter, or if you need assistance finding a Slingshot dealer, please visit the Slingshot web site at <http://www.polaris.com/en-us/slingshot> or contact our Slingshot Consumer Service Department by calling 1-855-863-2284.

This notice was mailed to you according to our most current registration information. If you no longer own your Slingshot vehicle, please contact your local Slingshot dealer to have the ownership information changed. The Slingshot Consumer Service Department cannot change ownership information without identification. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you have had these repairs performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information regarding reimbursement please contact your Slingshot dealer or the Slingshot Consumer Service Department using the information above.


If you believe that the Slingshot Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C. 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or on the web go to <http://www.safercar.gov>.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Slingshot is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,

Polaris On-Road Vehicles

PLEASE NOTE:

<p>This notice applies to Recall Campaign 18V321 - Brake Pedal Clevis Pin Clip. For additional information and to view open recalls on your vehicle, scan the QR code or go to: http://www.polaris.com/en-us/rider-support/on-road-recalls and enter your VIN, shown above the mailing address on this letter.</p>	
---	---