

---

**July 12, 2018**

Version 1

## **Incorrect Installation of the Takata Front Passenger's Airbag Inflator**

**Service bulletin 18-064 has been cancelled. All affected vehicles were combined with service bulletin 18-035, *Incorrect Installation of the Takata Front Passenger's Airbag Inflator*.**

END

**CUSTOMER INFORMATION:**The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.