



## Thor Motor Coach Recall Repair Instructions

Recall #	<b>18V-482 2018-383</b>		
Description/Title:	<b>Class C Outlaw 29J Rear Reflex Reflectors</b>		
Affected Product Line(s):	<b>Certain MY 2018/2019 Class C Outlaw 29J motorhomes</b>		
Service Campaign # :	<b>RC000157</b>	Released Date:	<b>08/14/2018</b>
Repair Code:	<b>TMCRC80474V</b>	Document Date:	<b>08/14/2018</b>
Time Allowed:	<b>0.2</b>	Document Revision:	<b>A</b>

### **Issue:**

It has been decided that on certain 2018/2019 Outlaw 29J motorhomes, the motorhome may be missing the rear reflex reflectors, which is a non-compliance of FMVSS/CMVSS 108. Without the required reflectors, the motorhome may be less visible to other drivers, increasing the risk of a crash and/or property damage.

### **Part(s) Required:**

**TMC Recall Kit Part #0425217**

*Recall Kit Includes: Two (2) Kaper II reflex reflectors  
Four (4) 1" x #6 self-tapping screws*

### **Instructions:**


1. Peel paper off adhesive tape on the back of the reflectors.

*(Continued on next page)*



## Thor Motor Coach Recall Repair Instructions

2. Insert two (2) 1" x #6 self-tapping screws in each reflector shown in Figure A.



(Figure A)

3. Install reflectors onto motorhome in locations shown in Figure B.



(Figure B)

4. Reference **TMC Print TFM5012** on next page for additional assembly view.

