

POSTED ON ISIS

OCT 04 2018

MAILED

OCT 05 2018

Compliance Dept.

Compliance Dept.

SERVICE PROCEDURE

18V-563 / 18E-044

OCTOBER 2018

SUBJECT: SAFETY RECALL

Wheelchair lifts on certain CE school bus models built 10 April 2014 thru 9 May 2018 with Ricon S Series and K Series Titanium Wheelchair Lifts, part numbers K200, K201, K550, K551, S200, S201, S550, and S551

DEFECT DESCRIPTION

The wheelchair lift positioning input cam may fail while the lift is in use, resulting in a disabled cutoff switch. If the cutoff switch is disabled and if the platform is raised up to the vehicle floor height, the platform can travel past the vehicle floor height. A platform that travels past the vehicle floor height may potentially cause the occupant to tip inwards, toward the vehicle, increasing the risk of injury.

MODELS INVOLVED

This safety recall involves certain CE school bus models built 10 April 2014 thru 9 May 2018 with Ricon S Series and K Series Titanium Wheelchair Lifts, part numbers K200, K201, K550, K551, S200, S201, S550, and S551.

ELIGIBILITY

This procedure applies ONLY to vehicles in which the customer has received a letter for NHTSA Recall 18V-563 / 18E-044. Also complete any other open campaigns listed on the International[®] Service PortalSM at this time.

PARTS / SERVICE / ADMINISTRATIVE INFORMATION

Ricon is managing this recall under NHTSA recall 18E-044. Please record the lift serial number and VIN and contact Ricon customer Service at (800) 322-2884 or by email at admin18E044@wabtec.com.

Each vehicle corrected in accordance with this campaign must be marked with a CTS-1075 Campaign Identification Label.

Complete the label and attach on a clean surface next to the vehicle identification number (VIN) plate.



NAVISTAR, INC.