


RECALL 18V678 / 2018-531 REMEDY INSTRUCTIONS

 FOREST RIVER	Make(s): ROCKWOOD & FLAGSTAFF Model(s): MANY Model Year(s): 2019	Repair Code: N/A Allotted Time: N/A Inspection Code: RC-007-05--002818 Allotted Time: 50 HRS
	Concern: The brake mounting flange is incorrectly oriented (clocked) on the axles in question. The brake (mounted on the flange) is therefore also incorrectly oriented.	Photo(s) Required: YES Prior Authorization Required: YES Part(s) Kit Number: N/A Part(s) Return: NO

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

INSPECTION:

STEP 1: TAKE PHOTOS OF EACH END OF THE AXLE AS REFERENCED IN FIGURE 1 & 2 BELOW.

STEP 2: TAKE PHOTOS OF EACH AXLE TAG.

STEP 3: SUBMIT PHOTOS TO WARRANTY@DEXTERAXLE.COM REFERENCING RECALL 18V678/2018-531. DEXTER WILL BE IN TOUCH WITH YOU ON FURTHER STEPS.



FIGURE 1



FIGURE 2

STEP 4: CLAIM INSPECTION CODE