

T680/T880 IMMI Seat Belt Webbing Not Sewn

Author: OF

2/8/2019

Title	18KWG: T680/T880 IMMI Seat Belt Webbing Not Sewn
Search Words	Seat belt
Bulletin No.	18KWG
What's New Abstract	Safety Recall – Parts are available - The webbing of certain IMMI seat belt buckle assemblies, provided for GraMag seats, may have been glued, but not sewn, allowing the seat belt to come apart. Failure to adequately restrain a vehicle occupant during a crash may increase the risk of injury.
Supplier	IMMI
Description	Recall 1B18KWG: T680/T880 IMMI Seat Belt Webbing Not Sewn
Release Date	
Introduction	Kenworth Truck Company has determined that a defect, which relates to motor vehicle safety, exists in certain T680 and T880 chassis manufactured between 08/18/2017 and 11/27/2017.
Situation	4501 chassis (4044 U.S. and 457 Canada), T680 and T880 vehicles built from 08/18/2017 through 11/27/2017 equipped with GraMag seats equipped with IMMI seat belt buckle assemblies. See the attached chassis list for specific chassis.
Resolution	Remove, inspect, and/or replace the buckle assembly as instructed in the attached Buckle Inspection/Replacement procedure.
It is a violation of Fe or noncompliance h	ederal law for a dealer to sell or lease new vehicles covered by this recall until the defect as been corrected.

Warranty	plus applicable File a long be include statement Inspecte 0.3 hou 18KWG File a long	Formation below. The buck NOT require replacement that are NOT replaced: code YYDDD. Passenge and reinstall both buckle and replace 1 buckle. blace 2 buckles. Use Quit circumstances (which mu	DD. Passenger's date code YYDDD. all both buckles.			
	CLAIM CODING					
	Failure Lo	ocation:	002-011-005	Work Accomplished:	21	
	Failure T	ype:	705	Responsibility Code:	05	
	SRT Cod	SRT Code:		Claim Type:	C	
	Vendor C	ode:	18KWG			
Parts	Parts are available from PACCAR Parts. Order parts as required after inspecting the buckles. Each vehicle may require 0, 1, or 2 buckles. Quantity Part Number Description As required S43-1043-100					
Labor						
Procedure						
Shipping						
Freight						
Contact						

Recall Template

Attachments	Buckle Inspection/Replacement procedure Dealer\Chassis List with affected seat part number U.S. Customer Letter Canada Customer Letter
-------------	---