

## **IMPORTANT: SAFETY RECALL REMINDER**

In October 2018, we notified you of a Safety Recall involving the wire harness on certain 2018 model year CRF250L motorcycles. At the time, we advised owners of the following:

**Honda has decided that certain 2018 model year CRF250L motorcycles may fail to conform with the requirements of Federal Motor Vehicle Safety Standard No. 108, Lamps, reflective devices, and associated equipment, and/or Federal Motor Vehicle Safety Standard No. 123, Motorcycle controls and displays. The wiring harness that controls several electrical components, such as the turn signal, headlight, taillight, horn, and instrument panel may have been damaged during the assembly process, potentially affecting component functionality. An improperly functioning headlight, taillight, and/or turn signals can reduce the visibility of the motorcycle rider and the motorcycle's visibility to traffic. An inoperable horn can prevent warning traffic of imminent danger, and a non-operating instrument panel will not display the speed or fuel gauge. A damaged wiring harness can also result in an engine stall and/or a no-start condition.**

According to our records, you have not yet had your affected motorcycle repaired. Please call your authorized Honda motorcycle dealer to schedule an appointment as soon as possible. This recall repair will be performed free of charge.

If your motorcycle has already been repaired, or if you no longer own this motorcycle, please let us know by filling out the included, postage paid, *Information Change Card*. We will update our records and stop sending you reminder notices.

If you have any questions about this recall, your authorized Honda motorcycle dealer will be happy to assist you.

Sincerely,

**American Honda Motor Co., Inc.  
Motorcycle Division**