

18V-465
In-Vehicle / In-App Communication – Safety Recall Reminder
04 Mar 2026

Title	Text	Short Text	Pop-Up
<p>BMW Safety Recall 18V-465: Engine Crankshaft Sensor</p>	<p>The engine's crankshaft sensor was not produced to specifications and, therefore, may not be able to process engine input signals. As a result, the engine may continue to run, but would do so in a reduced power mode, or it may run roughly. In some cases, it could stall, increasing the risk of a crash. A warning lamp would be illuminated in the instrument cluster.</p> <p>If any of these conditions occur, your vehicle may be experiencing this issue. If stalling occurs, pull off the road to a safe location. All occupants should carefully exit the vehicle and move to a safe location away from traffic. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.</p> <p>Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.</p> <p>Advise all drivers of this important information.</p> <p>For the latest updates to this recall, please visit bmwusa.com/recall.</p>	<p>Important BMW Safety Recall 18V-465: Engine Crankshaft Sensor. Contact an authorized BMW center immediately to get your vehicle repaired for FREE.</p>	<p>Important BMW Safety Recall 18V-465: Engine Crankshaft Sensor. Contact an authorized BMW center immediately to get your vehicle repaired for FREE. Dealer locator: bmwusa.com/dealer.</p>