CONDITION OF CONCERN

The driver side airbag inflator in your vehicle may be part of a small population of inflators that pose a higher risk of <u>explosion</u> in the event of a crash that causes an air bag deployment. Two inflators built at Takata on the same day as the driver side air bag inflator in your vehicle have <u>exploded</u> causing fatal injuries. An inflator explosion could result in <u>sharp metal fragments</u> striking the driver or other vehicle occupants, resulting in <u>SERIOUS INJURY OR DEATH.</u>

These are the same vehicles subject to Safety Recall 2318A.

SUBJECT VEHICLES

Model	VIN range	Build Date Range
2006 B-Series Truck	VIN list on MGSS	Vehicles with a specific B-Series Takata air bag manufactured in a finite date range

MANDATORY AIR BAG INFLATOR RETURN

All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MGSS and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

OWNER NOTIFICATION

Mazda will notify U.S. owners by overnight and certified mail (2 mailings) beginning January 18, 2018.

PARTS INFORMATION

Effective February 26, 2018, dealers will have to email the Dealer Assistance Group (DAG) to place an order for these airbag inflator parts. The DAG email address is: corpdag@mazdausa.com

NOTE: As per the Dealer Email from DAG Sent February 26th, 2018, the part you will order is a different part number. You will still receive the correct PNMC to install. Please do not attempt to order the PNMC for this recall as a stand-alone part.

Description	Part Number	Quantity	Notes
Driver Frontal Air Bag Inflator	1FT1-57-K00	1	Permanent Repair
	1FFF-57-K00 (please use for ordering)		
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

Recall 2218A – DAB "Permanent" Repair **CRITICAL **	Replacement of Driver Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1803A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K00 / 1 pc*
Labor Operation Number	YY794XRX
Labor Hours	0.4 hrs.
Sublet Code K1 – Towing	See Note below. DSM Authorization required
Sublet Code Z9 – Allowable Costs*	See Note below. DSM Authorization required

WARRANTY CLAIM PROCESSING INFORMATION

* From the Dealer E-mail released February 21, 2018

To provide a sufficient number of permanent remedy repair parts, Mazda has established the following two part numbers for Recall 2218A and 2318A repairs. Mazda is continually working with its suppliers to increase the number of available remedy parts for Recalls 2218A & 2318A, and for all of the Takata airbag recalls.

NOTE: The warranty claim Part Number Main Cause is not affected by this change.

2218A	1FFF-57-K00	B-SERIES DRIVER INFLATOR KIT
2318A	1FFF-57-K50A	B-SERIES PASSENGER INFLATOR KIT

<u>Note:</u> For K1 Sublet – we are allowing towing charges to be claimed to and from the dealer if Mazda Roadside Assistance (RSA) services were not arranged via the Mazda Customer Experience Center (CEC). Please keep in mind, warranty towing claim guidelines will apply and DSM Authorization required. *If customer is due a refund from towing costs, a dealer refund check copy is required to be attached, please use attachment ID D40 if used.*

For Z9 Sublet – Costs incurred must be pre-approved costs by your DSM or the Mazda Customer Experience Center for items such as remote repairs by a technician. Additional costs may be allowed. Please contact the warranty department for any questions on items that can or cannot be claimed. DSM Authorization is required. <u>If customer or dealer is due reimbursement from any other costs, a dealer refund check copy (customer) or proof of payment (dealer) is required to be attached, please use attachment ID D40 if used.</u>

RENTAL CAR INFORMATION

Mazda encourages all dealers to utilize MCVP vehicles for any alternate transport requests. We are requesting dealer understanding and partnership regarding rental and MCVP utilization. Please make every effort to utilize MCVP vehicles in place of rental use. Rental is covered if customer has no alternative means of transportation.

Rental Car Warranty Claim Information

Please submit rentals on a separate claim problem number as follows:

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code		A
Symptom Code		99
Damage Code		99
Part Number Main Cause	N/A	5555-22-18AR
Part Quantity	MCVP does not require claim	0
Labor Operation Code	submission	MM024XRX
Labor Hours		0
Sublet – Rental Car		
Sublet Invoice Number		Number from Rental Invoice or
		Dealer
		Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day
		for the number of days
		customer had rental
Sublet Text		Number of days rental
		car was supplied to

Rental expenses exceeding the two-day limit will require prior DSM Authorization, as outlined in the Mazda Rental Car Reimbursement Program policy. **NOTE: Please make every effort to** accommodate the vehicle owner with this critical recall.