

UPDATE APRIL 12, 2024, updated inflator part number

CONDITION OF CONCERN

The passenger side air bag inflator (recall 2318A) in this vehicle **must** be repaired at the same time as the driver side air bag inflator. Note: The driver side airbag inflator in your vehicle may be part of a small population of inflators that pose a higher risk of **explosion** in the event of a crash that causes an air bag deployment. Two inflators built at Takata on the same day as the driver side air bag inflator in your vehicle have **exploded** causing fatal injuries. **An inflator explosion could result in sharp metal fragments striking the driver or other vehicle occupants, resulting in SERIOUS INJURY OR DEATH.**

SUBJECT VEHICLES: These are the same vehicles subject to Safety Recall 2218A

Model	VIN range	Build Date Range
2006 B-Series Truck	VIN List on MGSS vehicles – see MGSS for VIN's	Vehicles with a specific B-Series Takata air bag manufactured within a finite date range

OWNER NOTIFICATION

Mazda notified customers by overnight and certified mail (2 mailings) beginning January 18, 2018.

MANDATORY AIR BAG INFLATOR RETURN: All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please follow instructions on MGSS under this campaign or through the Dealer Assistance Group website.

PARTS INFORMATION

Description	Part Number	Quantity	Notes	Scrap
Passenger Frontal Air Bag Inflator	1FT1-57-K50C	1	Permanent Repair	No, see return info above
Campaign Label	9999-95-065A-06	1 pack = 50 labels	Obtain in Mazda e-Store (no charge)	N/A

WARRANTY CLAIM PROCESSING INFORMATION



Do not process this claim without the correct photo attachments as the claim will not be paid with the wrong photos. Make sure the technician gives the warranty administrator the correct photos.

Recall 2318A – PAB “Permanent” Repair **CRITICAL**	Replacement of Passenger Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1804A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K50A / 1 pc
Labor Operation Number	YY795XRX
Labor Hours	0.7 hrs.
Attachment ID: D40	Photo from repair Step 14, Correctly installed inflator and Repair Order showing the VIN in the same Photo
Attachment ID: D01	Repair Order

RENTAL CAR INFORMATION

PLEASE CLAIM ANY RENTALS ON RECALL 2218A