

Latest Vehicle Concern Fixes



Vehicle	Customer Concern	Details and Status	Publication
XF Sportbrake 18MY	Restraints Control Module (RCM) Calibration Incorrect	A limited number of 2018 XF Sportbrake models have been built with the incorrect Restraints Control Module (RCM) calibration. Safety Recall H090 is being published to proactively correct the RCM calibration in the affected vehicles. All unsold vehicles must have this Recall performed before customer handover.	H090NAS1