

Toyota Motor North America, Inc.

Vehicle Safety & Compliance  
Liaison Office  
6565 Headquarters Drive  
Plano, TX 75024

January 14, 2019

## **AMENDED DEFECT INFORMATION REPORT (18V776)**

After additional investigation, Toyota has become aware that some vehicles originally included in this recall may not be equipped with a generation 5.5 SRS ECU produced by TRW that is the subject of this recall. These vehicles may be equipped with an SRS ECU produced by a different company that is not affected by this condition. Thus, Toyota is amending its Part 573 Report of November 1, 2018 concerning the SRS ECU issue on certain Toyota / Scion xA vehicles.

The description of Corrective Repair Action is revised as noted below to include an inspection to determine if a recalled vehicle contains an SRS ECU affected by the condition addressed by this recall:

### Description of Corrective Repair Action:

All known owners of the subject vehicles will be notified by first class mail to return their vehicles to a Toyota dealer. Dealers will check the part number of the SRS ECU to determine if the ECU is affected by the condition addressed by this recall. If the ECU is an affected one, dealers will replace the airbag control module with an improved one.