## **DEFECT INFORMATION REPORT**

573.6(c)(1)

Name of manufacturer:

Honda Manufacturing of Alabama, LLC

Manufacturer's agent:

John Turley

American Honda Motor Co., Inc.

1919 Torrance Blvd.

Torrance, CA 90501-2746

573.6(c)(2)

Identification of potentially affected vehicles:

Make/Model Description

Dates of Manufacture

Honda Pilot

Certain 2019 model year

10/19/2018 to 10/25/2018

KEVIEWED BY:
JOHN TURLEY
Nov-28-2018
Addr Turlay

Honda Ridgeline

Certain 2019 model year

10/19/2018 to 10/23/2018

573.6(c)(2)(iv)

Identification of affected component:

Component:

Rail R., Fr. Roof Side

Part No.:

64211-TG7-A000-H1

Country of Origin:

USA

Manufacturer:

Jefferson Southern Corporation

Address:

1000 Marquette Road

Rockmart, GA 30153

## Description of the basis for the determination of the recall population:

The recall population was determined based on manufacturing records. The production range reflects all possible vehicles that could potentially experience the problem.

## Description of how the vehicles being recalled differ from similar vehicles not included in the recall:

Supplier manufacturing records identified a specific production period of right front roof side rails affected by an improper manufacturing process. Similar vehicles not included in the recall were assembled with right front roof side rails manufactured outside of the suspect production period.

573.6(c)(3)

Total number of potentially affected vehicles:

403

Make/Model	Model Year	Number of Vehicles
Honda Pilot	2019	342
Honda Ridgeline	2019	61