



6555 Katella Avenue • Cypress • California • 90630-5101 • (714) 761-7300 • Fax (714) 229-7944

December 03, 2018

Chief Administrator
National Highway Traffic Safety Administration
Associate Administrator for Safety Assurance (NVS-215)
1200 New Jersey Avenue SE,
Washington, DC 20590

Regarding: Certain 2015 ~ 2018 model YZFR3, Radiator Hose Replacement, Factory Modification Campaign.

Dear Sir/Madam:

The purpose of this correspondence is to provide preliminary information required by 49 CFR 573 and the National Traffic and Motor Vehicle Safety Act regarding a defect notification campaign we are initiating. Provided via the recall portal are draft copies of the Owner's notification letter, for Agency approval, and the dealer technical bulletin. The envelope format and label has previously been approved by the Agency for prior campaigns.

1. Manufacturers Name: Yamaha Indonesia Motor Manufacturing
JI. DR. Rajiman Widyodiningrat
Pulo Gadung, Jakarta 13920. Indonesia

Imported Vehicle Distributor: Yamaha Motor Corporation, U.S.A.
6555 Katella Avenue
Cypress, California 90630

2. Vehicles Affected: Make: Yamaha
Model: YZFR3 Motorcycles
Years: 2015 ~ 2018

Nominal Engine Displacement: The YZFR3 is 320cc,

Production Period: Affected models were produced between 01/05/2015 –
11/30/2017

3. The campaign addresses an upper radiator hose. A crack may form on the radiator hose and coolant leakage can occur due to improper curing (“vulcanization”) of the hose material. If this occurs, coolant could get on the rear tire, causing slipping, which could lead to loss of control.

4. Total number of subject vehicles: Current estimate: 16,760 units. This will be updated in a supplemental report as we finalize the affected VIN range.
5. VIN Range: Tentative range will be supplied in forthcoming draft Technical Bulletin. Likewise, this will be updated in a subsequent report as data is confirmed.
6. The campaign involves the installation of a new upper radiator hose. In affected motorcycles, a crack may form on the radiator hose and coolant leakage can occur due to improper curing (“vulcanization”) of the hose material. Please refer to the draft Technical Bulletin which will be furnished to the Agency and Yamaha dealers upon completion describing the situation which is the subject of the campaign.
7. In late November, 2018 Yamaha Motor Corporation USA was informed by the manufacturer, Yamaha Indonesia Motor Manufacturing that such a situation exists. This was determined pursuant to a quality control review, testing and a review of foreign models that use a substantially similarly part design.

We anticipate commencing dealer/owner notification shortly after the owner’s notification letter is approved by NHTSA (draft copies of the Customer Notification Letter and Technical Bulletin is attached for your review), the affected VIN range is ascertained and the Technical Bulletin service procedure is confirmed and finalized by Yamaha service staff. Assuming the Agency can approve the letter within 5 days of receipt (perhaps December 17) we will have the letter and Technical Bulletin printed. Normal turn-around time is 3 working days for such printing. Hence the materials will be ready for mailing approximately December 21. Final copies of these notification documents will be forwarded to the Agency as soon as possible.

In the event we can answer any questions or provide supplemental information, please do not hesitate to contact me. My direct telephone number is 714-761-7842. The fax number is 714-229-7944. My email is brad_franklin@yamaha-motor.com.

Sincerely,

Bradley Franklin

Bradley Franklin
Manager, Government Relations

BRF/lf