

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 12, 2019

Ms. Cynthia Williams Ford Motor Company 330 Town Center Drive Dearborn, MI 48126 1200 New Jersey Avenue SE Washington, DC 20590

NEF-150JK 19V-435

Subject: Rear Suspension Toe Links May Fracture

Dear Ms. Williams:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FORD/EXPLORER/2011-2017

Mfr's Report Date: June 10, 2019

NHTSA Campaign Number: 19V-435

Components:

SUSPENSION:REAR

Potential Number of Units Affected: 1,194,173

Problem Description:

Ford Motor Company (Ford) is recalling certain 2011-2017 Explorer vehicles. The rear suspension toe links may fracture due to stress on the rear suspension.

Consequence:

A fractured rear toe link will cause a sudden change in vehicle handling and increase the risk of a crash.

Remedy:

Ford will notify owners, and dealers will replace the rear suspension to links, free of charge. The recall is expected to begin June 24, 2019. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 19S17.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Ford's proposed owner notification letter and it is currently being reviewed. You will be notified of any changes or concerns once our review is complete.

Please identify how this defect filing affects existing recall 16V245 (16S18).

Please be reminded of the following requirements:

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the rear suspension toe links. Please also provide the part number(s) of the recalled parts.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Acting Chief, Recall Management Division

Office of Defects Investigations

Enforcement

