

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 25, 2019

Mr. Gerrit Hurenkamp Director of Engineering Arcimoto Inc 2034 W. 2nd Ave Eugene, OR 97402

Subject: High Voltage System may Short

Dear Mr. Hurenkamp:

This letter serves to acknowledge Arcimoto Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ARCIMOTO/FUV/2019

Mfr's Report Date: November 4, 2019

NHTSA Campaign Number: 19V-791

Components:

ELECTRICAL SYSTEM:FUSES AND CIRCUIT BREAKERS ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: 13

Problem Description:

Arcimoto Inc. (Arcimoto) is recalling certain 2019 FUV vehicles. The braided shielding of the high-voltage harness may short against an energized component causing a main fuse to blow, resulting in a loss of drive power.

Consequence:

A loss of power can increase the risk of a crash.

Remedy:

Arcimoto will notify owners, and dealers will inspect the harness and replace it, as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Arcimoto customer service at 1-541-683-6293.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-150DM

19V-791

NHTSA is missing critical, required information for this safety recall. This information must be supplied through the NHTSA Recalls Portal within 5 working days of confirming its accuracy:

- Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate (49 CFR 573.6 (c)(8)(ii)).
- Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefore, and furnish a revised estimate. (49 CFR 573.6 (c)(8)(ii)).

If the components being replaced have a different part number than the original parts, your report must include (1) The name of the component or components, (2) A description of the component or components, and (3) The original part number of the component or components, if any. (49 USC 30119 (g)).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff Chief, Recall Management Division

Office of Defects Investigations

Enforcement

