OMB Control No.: 2127-0004

40

Part 573 Safety Recall Report

Manufacturer Name : Newmar Corporation Submission Date : MAY 20, 2019 NHTSA Recall No.: 19V-381 Manufacturer Recall No.: 19012

Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address: 355 North Delaware Street PO Box 30 Nappanee IN 46550 Company phone : 574-773-7791

Vehicle Information :

Vehicle 1:	2019-2019 Nev	vmar Essex			
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	NR				
Descriptive Information :	may be partially could reduce th distance. An inc the risk of a cra	y blocked restr te actuation time crease in stopp sh. Correction the relay valve l be done at no	ricting air ne of the ing distar : The bral will be re	flow to the l brakes and render the could occ ke relay valve	relay valve in the brake system brake chambers. This restriction esult in extended stopping cur without warning and increase e will be removed and inspected. In the inspection and replacement
Production Dates :	DEC 18, 2018 - 1	MAR 27, 2019			
VIN Range 1:		NR	End :	NR	□ Not sequential
Vehicle 2:	2019-2019 Nev	vmar King Aire	e		
Vehicle Type : Body Style :	BUSES, MEDIUN	M & HEAVY VE	HICLES		
Power Train :	NR				
Descriptive Information :	may be partially could reduce th distance. An inc the risk of a cra needed, the bra	y blocked restr le actuation tin crease in stopp sh. Correction	ricting air ne of the ing distar : The bral will be re	flow to the l brakes and render could occ ke relay valve	relay valve in the brake system brake chambers. This restriction esult in extended stopping cur without warning and increase e will be removed and inspected. In the inspection and replacement
	2019 King Aire		nes		
Production Dates :	2019 King Aire	= 14 motorhor	nes		





Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

19V-381

Part 573 Safety Recall Report

19V-381

Vehicle Type Body Style : Power Train :BUSES, MEDIUM & HEAVY VEHICLES Body Style : Power Train :NRDescriptive Information : ould reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. London Aire = 9 motorhomesProduction Dates : Body Style : Body Style : Power Train :NREnd : NRNRChicle Type : Body Style : Dower Train :NREnd: NROn certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed. The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed. And inspected needed, the brake relay valve will be removed. Both the inspection and replacement of the valve will be done at no charge. 2020 Dutch Star=2 motorhomesProd	Vehicle 3	2019-2019 Ne	wmar I ondor	Aire	
Body Style : Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brake and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and replacement of the valve will be done at no charge. London Aire = 9 motorhomes Production Dates : DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR End : NR Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake trapy valve in the brake system may be partially blocked restricting diaf flow to the brake sould in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and replacement of the valve will be done at no charge. 2020 Dutch Star=2 motorhomes Production Dates : DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR Edition Type : Buses. MEDIUM & HEAVY VEHICLES Body Style : On certain motorhomes, an orifice within the brake relay val					
Descriptive Information: On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be done at no charge. London Aire = 9 motorhomes Production Dates: DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR End : NR Vehicle 4 : 2020-2020 Newmar Dutch Star Vehicle 5 : 2020-2020 Newmar Dutch Star Vehicle 6 : 2020-2020 Newmar Dutch Star Vehicle 7 Concertain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brake relay valve in the brake system may be partially blocked restricting air flow to the inspection and replacement of the valve will be done at no charge. Production Dates: DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR End : NR Production Dates: DEC 18, 2018 - MAR 27, 2019 Not sequentia Vehicle 5: 2019-2019 Newmar Mou					
may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and Increas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. London Aire = 9 motorhomes Production Dates: DEC 18, 2018 - MAR 27, 2019 VIN Range 1: Begin: NR End: NR Power Train: NR Body Style: Power Train: Power Train: NR Descriptive Information: On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and lincreas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected will be done at no charge. 2020 Dutch Star=2 motorhomes Production Dates: DEC 18, 2018 - MAR 27, 2019 VIN Range 1: Begin: NR End: NR NR Dotto star=2 motorhomes. Production Dates: DEC 18, 2018 - MAR 27, 2019 Vehicle	Power Train :	NR			
VIN Range 1 : Begin : NR End : NR Indiana Vehicle 4 : 2020-2020 Newmar Dutch Star Vehicle Type : Body Style : Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2020 Dutch Star=2 motorhomes Production Dates : DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR End : NR Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES Body Style : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of use partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extende	Descriptive Information :	may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r	tricting air flow to the bra ime of the brakes and resu- ping distance could occur n: The brake relay valve w e will be replaced. Both th to charge.	ake chambers. This restriction ult in extended stopping without warning and increase vill be removed and inspected. I
Vehicle 4: 2020-2020 Newmar Dutch Star Vehicle Type : Body Style : Bower Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increas the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2020 Dutch Star=2 motorhomes Production Dates : DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR End : NR Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be created. The brake relay valve will be created at the valve will be done at no charge. 2019 Mountain Aire=10 motorhomes 2019 Mountain Aire=10 motorhomes	Production Dates :	DEC 18, 2018 -	- MAR 27, 201	9	
Vehicle Type : Body Style : Body Style : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2020 Dutch Star=2 motorhomes Production Dates : DEC 18, 2018 - MAR 27, 2019 VIN Range 1 : Begin : NR Rend : NR Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES Body Style : Power Train : Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake system in may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed and inspected needed, the brake relay valve will be removed. Both the	VIN Range 1:	Begin :	NR	End: NR	Not sequential
VIN Range 1: Begin: NR End: NR Not sequential Vehicle 5: 2019-2019 Newmar Mountain Aire Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES Body Style: Power Train: Power Train: NR Descriptive Information: On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2019 Mountain Aire=10 motorhomes	Body Style : Power Train :		tonhomos on		
Vehicle 5: 2019-2019 Newmar Mountain Aire Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES Body Style : Power Train : Power Train : NR Descriptive Information : On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2019 Mountain Aire=10 motorhomes		may be partial could reduce t distance. An im the risk of a cr needed, the br of the valve wi 2020 Dutch St	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r ar=2 motorho	tricting air flow to the bra ime of the brakes and resu- oping distance could occur n: The brake relay valve w e will be replaced. Both th no charge. mes	ake chambers. This restriction ult in extended stopping without warning and increase vill be removed and inspected. It
Vehicle Type : Body Style : Power Train :BUSES, MEDIUM & HEAVY VEHICLES NRDescriptive Information : ould reduce the actuation time of the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance. An increase in stopping distance could occur without warning and increase the risk of a crash. Correction: The brake relay valve will be removed and inspected needed, the brake relay valve will be replaced. Both the inspection and replacement of the valve will be done at no charge. 2019 Mountain Aire=10 motorhomes		may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2020 Dutch Sta DEC 18, 2018	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r ar=2 motorho - MAR 27, 201	tricting air flow to the bra ime of the brakes and resu- ping distance could occur n: The brake relay valve w e will be replaced. Both th to charge. mes 9	ake chambers. This restriction ult in extended stopping without warning and increase vill be removed and inspected. In he inspection and replacement
of the valve will be done at no charge. 2019 Mountain Aire=10 motorhomes		may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2020 Dutch Sta DEC 18, 2018	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r ar=2 motorho - MAR 27, 201	tricting air flow to the bra ime of the brakes and resu- ping distance could occur n: The brake relay valve w e will be replaced. Both th to charge. mes 9	ake chambers. This restriction ult in extended stopping without warning and increase vill be removed and inspected. I
	VIN Range 1 : Vehicle 5 : Vehicle Type : Body Style : Power Train :	may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2020 Dutch St DEC 18, 2018 - Begin : 2019-2019 Ne BUSES, MEDIU NR On certain mor may be partial could reduce t distance. An in the risk of a cr	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r ar=2 motorho - MAR 27, 201 NR wmar Mounta IM & HEAVY V torhomes, and ly blocked res he actuation t acrease in stop ash. Correctio	tricting air flow to the bra ime of the brakes and resu oping distance could occur n: The brake relay valve w e will be replaced. Both the no charge. mes 9 End : NR ain Aire ZEHICLES orifice within the brake resu tricting air flow to the bra ime of the brakes and resu oping distance could occur n: The brake relay valve w	Ake chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. If the inspection and replacement Not sequential Play valve in the brake system alter chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. If
Production Dates : DEC 18, 2018 - MAR 27, 2019	VIN Range 1 : Vehicle 5 : Vehicle Type : Body Style : Power Train :	may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2020 Dutch Sta DEC 18, 2018 Begin : 2019-2019 Ne BUSES, MEDIU NR On certain mot may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r ar=2 motorho - MAR 27, 201 NR wmar Mounta IM & HEAVY V torhomes, an ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv ill be done at r	tricting air flow to the braime of the brakes and result oping distance could occur n: The brake relay valve will be replaced. Both the no charge. mes 9 End : NR ain Aire ZEHICLES orifice within the brake result orifice within the brake result ime of the brakes and result oping distance could occur n: The brake relay valve will be replaced. Both the no charge.	Ake chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. In the inspection and replacement Not sequential Play valve in the brake system alter chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. I
VIN Range 1 : Begin : NR End : NR 🗌 Not sequentia	VIN Range 1 : Vehicle 5 : Vehicle Type : Body Style : Power Train : Descriptive Information :	may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2020 Dutch St DEC 18, 2018 - Begin : 2019-2019 Ne BUSES, MEDIU NR On certain mor may be partial could reduce t distance. An in the risk of a cr needed, the br of the valve wi 2019 Mountain	ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv all be done at r ar=2 motorho - MAR 27, 201 NR wmar Mounta JM & HEAVY V torhomes, an ly blocked res he actuation t acrease in stop ash. Correctio ake relay valv all be done at r n Aire=10 mo	tricting air flow to the bra ime of the brakes and resu oping distance could occur n: The brake relay valve w e will be replaced. Both the no charge. mes 9 End : NR ain Aire ZEHICLES orifice within the brake resu tricting air flow to the bra ime of the brakes and resu oping distance could occur n: The brake relay valve w e will be replaced. Both the no charge. torhomes	Ake chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. If the inspection and replacement Not sequential Play valve in the brake system alter chambers. This restriction alt in extended stopping without warning and increase will be removed and inspected. If

Description of Defect :

Description of the Defect :	On certain motorhomes, an orifice within the brake relay valve in the brake system may be partially blocked restricting air flow to the brake chambers. This restriction could reduce the actuation time of the brakes and result in extended stopping distance.
FMVSS 1 :	121 - Air brake systems
FMVSS 2 :	NR
Description of the Safety Risk :	An increase in stopping distance could occur without warning and increase the risk of a crash.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	

Supplier Identification :

Component Manufacturer

Name: Spartan Motors USA, INC

Address : 1541 Reynolds Rd. Charlotte MICHIGAN 48813 Country : United States

Chronology:

On 5/16/2019, Spartan Motors USA gave Newmar notice of defect on Spartan chassis. On 5/20/2019, Newmar is giving notice of defect on Newmar motor-homes built on Spartan Chassis.

Description of Remedy :

Description of Remedy Program :	The brake relay valve will be removed and inspected. If needed, the brake relay valve will be replaced.
How Remedy Component Differs from Recalled Component :	
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Recall Schedule :	On or before 07/19/2019, customer/dealers will be mailed out to
	customer/dealers.
Planned Dealer Notification Date :	JUL 19, 2019 - JUL 19, 2019
Planned Owner Notification Date :	JUL 19, 2019 ⁻ JUL 19, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573