OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-439

Manufacturer Name: LA West Inc.
Submission Date: MAY 27, 2020
NHTSA Recall No.: 19V-439
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: LA West Inc.

Address: 196 Crawford Road

Statesville NC 28625

Company phone: 704-498-4940

Population:

Number of potentially involved: 15 Estimated percentage with defect: 95 %

Vehicle Information:

Vehicle 1: 2018-2019 Ford Transit

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN
Power Train : GAS

Descriptive Information: LA West reviewed all purchases made to SMI for said hatch during the time frame

provided by the Recall Notice from SMI.

Production Dates: AUG 01, 2018 - APR 01, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: SMI has determined that some Transpec Glass Hatches may contain edge

defects (chips) in the glass panels that have resulted from the manufacturing

process

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Hot/cold and vibration/shock can create stress concentrations at these edge

defects that may result in fracture and failure of the tempered glass if edge

damage is present

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Specialty Manufacturing, Inc

Address: 13501 S Ridge Dr

Charlotte NORTH CAROLINA 28273

Country: United States

Chronology:

SMI advised that there may be a defect in the hatches that were purchased from them during a specific time frame. We immediately investigated to determine how many hatches were purchased and which vehicles they were installed in. Once complete we started the Recall process.

Description of Remedy:

Description of Remedy Program: Transpec glass hatch replacement kits will be sent to you upon request

and will include complete instructions on the removal and re-installation of the defective components. Removal and re-installation of each Transpec glass hatch lid can be accomplished in 15 minutes, for which SMI will

reimburse installers \$30.00 for each remedied hatch.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition Upon receiving notification from SMI, all remaining inventory at LA West

was Corrected in Production: was guarantined and inspected.

Recall Schedule:

Description of Recall Schedule: Will send out a letter to all the dealers effected by this recall, as well as

notify by written letter all owners if vehicles have been sold

Planned Dealer Notification Date: JUN 17, 2019 - AUG 17, 2019 Planned Owner Notification Date: JUN 17, 2019 - AUG 17, 2019

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report	19V-439	Page 3
* NR - Not Reported		
The information contained in this report was submitted		