The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :SVO Group IncSubmission Date :JUN 18, 2019NHTSA Recall No. :19V-466Manufacturer Recall No. :19E-009

Manufacturer Information :

Manufacturer Name : SVO Group Inc Address : 2503 Ada Dr. Elkhart IN 46514 Company phone : 5742959359

Vehicle Information :

 Vehicle 1:
 2017-2018 FORD E-450 / E-350

 Vehicle Type :
 Body Style :

 Body Style :
 NR

 Power Train :
 NR

 Descriptive Information :
 RECORD OF SEVERAL NUMBERS SOL TO SVO GROUP DURING AFFECTED TIME FRAME

 Production Dates :
 JUN 01, 2017 - DEC 31, 2018

 VIN Range 1 : Begin :
 NR
 End : NR
 Not sequential

Description of Defect :

Description of the Defect :MIRROR MONITOR COULD POSSIBLY POWER UP WITHOUT LOADING USER
DEFINED SETTINGSFMVSS 1 :NRFMVSS 2 :NRDescription of the Safety Risk :MIRROR COULD SHOW INVERTED IMAGE ALLOWING OUTSIDE NOISE INTO
CABDescription of the Cause :NRIdentification of Any Warning
that can Occur :NR

Supplier Identification :

Component Manufacturer

Name: ASA ELECTRONICS LLC



Number of potentially involved :

Estimated percentage with defect : 100 %

Population:

52

19V-466

Part 573 Safety Re	call Report	19V-466	Page 2
Address : 2602 MARIA DRIVE Elkhart INDIANA 46514 Country : United States			
Chronology : JUNE 2017 TO DECEMBER 2018 SO LETTERS A,B,C WITH POTENTIAL D			VITH
Description of Remedy : Description of Remedy Program :	ASA HAS A HARNESS RELAY CA	APACITOR KIT TO REPAIR ISSUE	
How Remedy Component Differs		REPAIRED AT ASA ELECTRONICS	
Identify How/When Recall Condition was Corrected in Production :	ONCE DEFECT WAS DISCOVER WITH AFFECTED SERIAL NUM		MM
Recall Schedule :			
Description of Recall Schedule : Planned Dealer Notification Date : Planned Owner Notification Date :			

* NR - Not Reported