

Part 573 Safety Recall Report

19V-500

Manufacturer Name : Honda (American Honda Motor Co.)**Submission Date :** JUL 26, 2019**NHTSA Recall No. :** 19V-500**Manufacturer Recall No. :** S5B, W59**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 1-888-234-2138

Population :

Number of potentially involved : 1,558

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2013-2013 Acura ILX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : NOV 07, 2012 - NOV 07, 2012

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2015-2015 Acura RDX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership

warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : APR 03, 2014 - APR 03, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 3 : 2005-2005 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 49.

Production Dates : JUL 26, 2004 - JUN 10, 2005

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2006-2006 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently

subject to an open driver's airbag inflator recall. The number of affected units is 32.

Production Dates : AUG 31, 2005 - JUL 07, 2006

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2007-2007 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 17.

Production Dates : SEP 13, 2006 - MAY 21, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2008-2008 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 17.

Production Dates : JUN 21, 2007 - DEC 03, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 7 : 2009-2009 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 7.

Production Dates : MAR 28, 2008 - MAR 19, 2009

VIN Range 1 : Begin : NR

End : NR

Not sequential

Vehicle 8 : 2010-2010 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 5.

Production Dates : JUN 03, 2009 - APR 07, 2010

VIN Range 1 : Begin : NR

End : NR

Not sequential

Vehicle 9 : 2012-2012 Acura RL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is

further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : MAR 20, 2012 - MAR 20, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 10 : 2009-2009 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : MAR 26, 2009 - MAR 26, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 11 : 2010-2010 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired

with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 3.

Production Dates : OCT 28, 2009 - JUL 23, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 12 : 2011-2011 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : OCT 08, 2010 - OCT 08, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 13 : 2012-2012 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 5.

Production Dates : MAR 23, 2011 - MAY 11, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 14 : 2013-2013 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : JUL 31, 2013 - JUL 31, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 15 : 2014-2014 Acura TL

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : FEB 19, 2014 - FEB 19, 2014

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 16 : 2010-2010 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient

supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 2.

Production Dates : MAR 02, 2010 - MAY 19, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 17 : 2012-2012 Acura ZDX

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : AUG 11, 2011 - AUG 11, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 18 : 2007-2007 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing

a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 279.

Production Dates : JUL 25, 2006 - SEP 17, 2007

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 19 : 2008-2008 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 284.

Production Dates : AUG 23, 2007 - SEP 30, 2008

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 20 : 2009-2009 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 136.

Production Dates : AUG 18, 2008 - SEP 11, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 21 : 2010-2010 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 133.

Production Dates : AUG 19, 2009 - OCT 02, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 22 : 2011-2011 Honda CR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 175.

Production Dates : AUG 23, 2010 - NOV 22, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 23 : 2011-2011 Honda CR-Z

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups

11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : NOV 26, 2010 - NOV 26, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 24 : 2012-2012 Honda CR-Z

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : APR 17, 2012 - APR 17, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 25 : 2013-2013 Honda CR-Z

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy

part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 2.

Production Dates : NOV 15, 2012 - MAR 27, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 26 : 2015-2015 Honda CR-Z

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 3.

Production Dates : JUN 17, 2015 - JUL 15, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 27 : 2009-2009 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 71.

Production Dates : JUL 29, 2008 - AUG 18, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 28 : 2010-2010 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 43.

Production Dates : SEP 04, 2009 - OCT 12, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 29 : 2011-2011 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 22.

Production Dates : NOV 08, 2010 - JUL 27, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 30 : 2012-2012 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order,

Descriptive Information : the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 27.

Production Dates : SEP 18, 2011 - JUN 28, 2012

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 31 : 2013-2013 Honda Fit

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 26.

Production Dates : JUL 17, 2012 - DEC 06, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 32 : 2013-2013 Honda Fit EV

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific

to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : APR 11, 2013 - APR 11, 2013

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 33 : 2010-2010 Honda Insight

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 30.

Production Dates : FEB 18, 2009 - JUL 27, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 34 : 2011-2011 Honda Insight

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 3.

Production Dates : NOV 12, 2010 - FEB 22, 2011

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 35 : 2013-2013 Honda Insight

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 3.

Production Dates : NOV 19, 2012 - DEC 05, 2012

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 36 : 2007-2007 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 65.

Production Dates : JUN 08, 2006 - MAY 29, 2007

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 37 : 2008-2008 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 73.

Production Dates : JUN 08, 2007 - JUL 17, 2008

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 38 : 2009-2009 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 11.

Production Dates : AUG 28, 2008 - JUL 22, 2009

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 39 : 2010-2010 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership

warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 15.

Production Dates : OCT 07, 2009 - JUN 05, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 40 : 2011-2011 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 2.

Production Dates : JUN 17, 2010 - DEC 02, 2010

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 41 : 2012-2012 Honda Ridgeline

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently

subject to an open driver's airbag inflator recall. The number of affected units is 3.
Production Dates : DEC 08, 2011 - MAY 23, 2012

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 42 : 2013-2013 Honda Ridgeline
Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 3.

Production Dates : JAN 02, 2013 - JUL 17, 2013

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 43 : 2014-2014 Honda Ridgeline
Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, the fifth phase of the Takata DIRs that affect the subject vehicles (Priority Groups 11-12) are not scheduled until late 2019. However, in consideration of a sufficient supply of final remedy inflators, and upon consultation with the NHTSA, Honda is further accelerating the launch of the remedy for these vehicles ahead of the late 2019 scheduled Takata DIRs. The recall population was determined based on dealership warranty, repair order, and service parts records. The production range reflects all possible vehicles that could potentially experience the problem. This recall is specific to vehicles that received a PSDI-5 driver's airbag inflator either as a recall remedy part or as a replacement service part (replacement driver's airbag module containing a PSDI-5 inflator). Similar vehicles not included in this recall either were repaired with a driver's airbag inflator from an alternative manufacturer, or are currently subject to an open driver's airbag inflator recall. The number of affected units is 1.

Production Dates : JUN 25, 2014 - JUN 25, 2014

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect :

Description of the Defect : According to the May 4, 2016 Amendment to the November 3, 2015 Consent Order, Takata agreed to conduct recalls on a rolling basis for a defect in all driver and passenger inflators that contain a PSAN-based propellant, and do not contain a moisture-absorbing desiccant. Specifically, a defect related to motor vehicle safety may arise in some of the subject non-desiccated PSAN inflators due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures, and high temperature cycling. Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning
that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : T.K. Global LLC

Address : 111 Peyerk Court
Romeo MICHIGAN 48065

Country : United States

Chronology :

May 29, 2019

In consideration of a sufficient supply of final remedy inflators, Honda consulted with the NHTSA about advancing the recall launch of Priority Groups 11-12 vehicles.

June 20, 2019

Honda determined that a defect related to motor vehicle safety existed and decided to conduct a safety recall ahead of the fifth phase of the Takata DIRs scheduled for late 2019.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to an Acura or Honda automobile dealer. The dealer will replace the driver's airbag inflator with a new inflator, free of charge.

How Remedy Component Differs from Recalled Component : Driver's airbag inflator (PSDI-5), driver's airbag inflator (PSDI-5), part number: CR-V 77810-SWA-A70ZA, CR-Z 77810-SZT-A80ZA, Fit / Fit EV 77810-TK6-A80ZA, Insight 77810-TK6-A80ZC, Ridgeline 77810-SJC-A60ZA, ILX 77810-TX6-A80ZA, RDX 77810-TX4-A40ZA, RL 77810-SJA-A82ZA, TL 77810-TX4-A80ZA, ZDX 77810-TX4-A80ZA.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer notification is expected to begin on or about June 28, 2019. Owner notification is expected to begin on or about August 12, 2019.

Planned Dealer Notification Date : JUN 28, 2019 - NR

Planned Owner Notification Date : AUG 12, 2019 - NR

* NR - Not Reported