

Part 573 Safety Recall Report

19V-682

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** SEP 26, 2019**NHTSA Recall No. :** 19V-682**Manufacturer Recall No. :** H256**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 241

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

Mahwah NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2019-2020 JAGUAR F-TYPE

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : Certain 2019 and 2020 Model Year Jaguar F-TYPE vehicles fitted with 18 inch rear tires, where the tire placard label located on the driver's door opening incorrectly states the wrong rear tire size for the vehicle.

Production Dates : OCT 18, 2018 - AUG 27, 2019

VIN Range 1 : Begin : SAJDD5EV0KCK62241 End : SAJDD1GX1LCK66873 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : A concern has been identified on certain 2019 and 2020 Model Year Jaguar F-TYPE vehicles fitted with 18 inch rear tires, where the tire placard label located on the driver's door opening incorrectly states the wrong rear tire size for the vehicle.

Vehicles where the label does not have the correct rear tire size stated on the tire placard label will not comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 110 - Tire Selection and Rims for Passenger Cars.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Where the tire placard label states the incorrect tire size, the customer may fit a tire with dimensions that are not to the as designed intent which may cause a change in the vehicle handling characteristics and increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : Jaguar Land Rover Limited
Address : Abbey Road
Whitley, Coventry FOREIGN STATES CV3 4LF
Country : United Kingdom

Chronology :

Jaguar Land Rover first identified a concern with the tire placard label during a Government Regulations Coordinator (GRC) vehicle audit event at the Castle Bromwich vehicle assembly plant. Following plant investigations, a regulatory Stop Shipment was implemented on August 29, 2019.

On September 03, 2019 the Jaguar Land Rover Product Safety and Compliance Committee (PSCC) opened an investigation to review the concern. Engineering investigated the concern and confirmed the error on the tire placard for the rear tire size originated in the engineering design release phase. On September 17, 2019 the PSCC agreed that the matter be progressed to the Recall Determination Committee (RDC).

On September 19, 2019, the RDC determined that the condition represented a compliance concern and affected vehicles do not fully meet the requirements of FMVSS 110 Tire Selection and Rims for Passenger Cars. A non-compliance recall will be conducted to correct this error.

There have been no reports of accidents or injuries as a result of this concern.

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Jaguar authorized repairer, who will attach a tire placard label that states the correct rear tire size.

There will be no charge to owners for this repair.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before November 20, 2019. Notifications to dealers will occur on October 10, 2019.

Planned Dealer Notification Date : OCT 10, 2019 - OCT 10, 2019

Planned Owner Notification Date : NOV 20, 2019 - NOV 20, 2019

* NR - Not Reported