

Part 573 Safety Recall Report

19V-829

Manufacturer Name : Daimler Trucks North America LLC**Submission Date :** NOV 19, 2019**NHTSA Recall No. :** 19V-829**Manufacturer Recall No. :** FL-840**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 2

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2020 Freightliner Econic SD

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Certification labels on certain Freightliner Econic SD Vehicles containing incorrect GAWR information.

Production Dates : AUG 08, 2019 - AUG 08, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : On the affected vehicles the vehicle certification label contains the incorrect information and thus fails to comply with the requirements of Federal Motor Vehicle Safety Standard No. 120, "Tire Selection and Rims for Motor Vehicles Other Than Passenger Cars." The Gross Axle weight rating (GAWR), states 8000 Kgs, 18000 lbs, however the steer tires are only rated for 17,640 lbs. The error was due to miscalculation in the conversion from Kgs to lbs.

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : Incorrect weight rating information on the certification labels could result in potential overloading of the axles and increase the likelihood of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

Late September 2019, during development of the service literature, it was identified that the GAWR label may be incorrect. October 2019, DTNA opens an investigation to identify potential field exposure. November 2019, DTNA identified that there were vehicles in the field requiring repairs with new labels and tires. November 12, 2019 DTNA determined that the labels did not comply with the certification requirements set forth in FMVSS 120, therefore decided to conduct a voluntary compliance recall.

Description of Remedy :

Description of Remedy Program : Field service indicated that all vehicles in the population have been repaired. DTNA will ensure that repairs were performed with no cost to customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : All the vehicles in the population have been repaired. DTNA will not be notifying customers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported