



Audi

AUDI DEALER COMMUNICATION

Advance Notice – Safety Recall 69S8 / Driver Frontal Airbag Inflator (Takata)

This notice is for:

- ✓ Dealer Principal
- ✓ General Manager
- ✓ Sales Managers

- ✓ Service Manager
- ✓ Parts Manager
- ✓ Service Advisor

- ✓ Warranty Administrator
- ✓ Technicians

Date: February 07, 2019

Issue: The driver airbag may explode in a crash with airbag deployment. Sharp metal fragments can hit people and cause serious injury or death.

- Repair:**
- REPAIR NOT YET AVAILABLE – February 08, 2019
 - When parts become available, dealers will replace the driver frontal airbag inflator
 - Check daily campaign open inventory report or OMD for affected vehicles in inventory

Notes: Affected vehicles: Certain 2017 MY Audi R8 Spyder and Audi R8 Coupe and Certain 2016-2017 MY Audi TT Roadster and Audi TT Coupe equipped with a Takata driver frontal airbag (USA: 6,500 / CANADA 1,190)

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.