

GM CUSTOMER CARE AND AFTERSALES  
DCS5271  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 6, 2020

Subject: N182206630-02 - Safety Recall  
Airbag Inflator Rupture  
Revised Service Procedure

Models: 2010-2011 Chevrolet Malibu

To: All General Motors Dealers

This bulletin has been updated in the service procedure section for the airbag return location instructions. Please discard all previous copies of N182206630.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES