


## SAFETY RECALL VO7 ADJUSTABLE BRAKE PEDAL

## REINFORCEMENT OF REPAIR PROCEDURE

Based on recent investigations we have found instances of the repair procedure for Safety Recall V07 not being performed correctly which could create reduced clearance between the accelerator pedal and the floor mats.

Please pay special attention to step 3 on page 6 of the Dealer Instructions. If the electrical connector is not disconnected this could cause difficulty in getting the pedal to align properly for reassembly.



When performing step 12 on page 9 of the Dealer Instructions it is important to ensure that per figure 11 the "Upper Edge Lip" is fully engaged. Failure to do so could result in the pedal not having the intended clearance between it and the floor mat.

