



Parts Bulletin

TITLE:

**Recall R19931: Front Seat Rail Flange Nuts
Model Year 2018 – 2019 XC60 & S90**

GROUP: 1	CAT/NO: R19931	REFERENCE BULLETINS: QB-R19931	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2019-03-20	STATUS DATE: 2019-03-20
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB-R19931

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R19931 on certain model year 2018 – 2019 XC60 and S90 vehicles.

Volvo has identified that the drivers and passengers front seat rail rear flange nuts may be missing. This condition can compromise the front seat structure and position, and increase the risk of injury to the seat occupants in a crash.

The corrective action is to inspect the driver and passenger front seat rail rear flange nuts and verify that they are installed. If the flange nuts are installed no further action is necessary. If flange nuts are missing install them per the attached instructions.

A total of 2,297 U.S. and 6 Canadian vehicles are eligible for this recall.

The following part number applies:

Part Number	Description	Qty
30622683	Flange Nut	1 – 4 as needed

Volvo anticipates most vehicles eligible for this recall will need an inspection only. Please only order as needed to ensure adequate stock for all retailers.