View Message

Sent on	04	12	2019	Expires on	04	14	2019	
From	Service Operations							
Subject	UPDATE: Revision for SB 19-045, Safety Recall: 3.5L V6 Timing Belt							

Version 1 of Service bulletin 19-045, *Safety Recall: 3.5L V6 Timing Belt,* which posted today (April 12, 2019), has an error in step 5 of the INSPECTION procedure.

Currently reads:

• the lot code is not visible, go to step 8.

Should read

• the lot code is not visible, go to TIMING BELT REPLACEMENT.

We will be posting a new version of the bulletin today. As a reminder, please always download the latest version of any service bulletin before beginning any repairs. We apologize for any confusion and inconvenience this may have caused.

Joshua Stone Manager - Service Publications (310) 783-3763