

View Message

Sent on 04 12 2019 **Expires on** 04 12 2019

From Service Operations

Subject UPDATE: Revision coming soon for SB 19-045, Safety Recall: 3.5L V6 Timing Belt

Version 1 of Service bulletin 19-045, *Safety Recall: 3.5L V6 Timing Belt*, which posted today (April 12, 2019), has an error in step 5 of the INSPECTION procedure.

Currently reads:

- the lot code is not visible, go to step 8.

Should read:

- the lot code is not visible, go to **TIMING BELT REPLACEMENT**.

We will be posting a new version of the bulletin today. We apologize for any confusion and inconvenience this may have caused.