

## View Message

<b>Sent on</b>	04	12	2019	<b>Expires on</b>	04	12	2019
<b>From</b>	Service Operations						
<b>Subject</b>	UPDATE: Revision for SB 19-026, Safety Recall: 3.5L V6 Timing Belt						

Version 1 of Service bulletin 19-026, *Safety Recall: 3.5L V6 Timing Belt*, which posted today (April 12, 2019), has an error in step 5 of the INSPECTION procedure.

Currently reads:

- the lot code is not visible, go to step 8.

Should read:

- the lot code is not visible, go to **TIMING BELT REPLACEMENT**.

We will be posting a new version of the bulletin today. We apologize for any confusion and inconvenience this may have caused.