VOLVO CAR SERVICE AND PARTS BUSINESS



Quality Bulletin

TITLE: Recall R29936: Coolant Bleeder Hose (Engine Side) Model Year 2016 XC90

GROUP:	CAT/NO:	ISSUING DEPARTMENT:		CAR MARKET:		
	R19931	Warranty		United States and Canada		
REFERENCE BULLETINS:					ISSUE DATE:	STATUS DATE:
PB R29936					2019-04-17	2019-04-17
Service Personnel:		SERVICE	SERVICE	WARRANTY	Page 1 of 3	
Read and initial		MANAGER	WRITER	ADMINISTRATOR		

"Right first time in Time"

BULLETIN REFERENCE PB R29936

- A. RECALL R29936 DESCRIPTION
- **B. VEHICLES INVOLVED**
- C. PARTS INFORMATION/PARTS RETURN
- **D. OWNER NOTIFICATION**
- E. VEHICLES IN RETAILER INVENTORY
- F. RETAILER RESPONSIBILITY
- G. CAMPAIGN REIMBURSEMENT PROCEDURES
- H. TECHNICIAN COMPETENCY REQUIREMENT
- I. RETAILER ALLOWANCE

A. RECALL R29936 DESCRIPTION

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R29936 on model year 2016 XC90 vehicles.

Volvo has identified that the coolant bleeder hose (engine side) may degrade over time and crack due to heat and humidity load. This condition can create a coolant leak, and also pose a risk of coolant leaking on the catalytic converter. If the coolant leak goes unnoticed, coolant may accumulate in the catalytic converter heatshield insulation and, in a worst case scenario, over time this might result in a fire in the engine compartment area when the vehicle is stationary.

The corrective action is to replace the engine side coolant bleeder hose.

A total of 34,006 U.S. and 2,721 Canadian vehicles are eligible for this recall.



B. VEHICLES INVOLVED

NOTE: RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS RECALL.

Vehicle eligibility must be confirmed:

• Vehicle Inquiry - Vehicle Warranty where the message "Recall R29936 Coolant Bleeder Hose" will appear for eligible vehicles or check eligibility in TIE.

All vehicles should be checked for any incomplete recalls or service campaigns or service upgrades. All open Recall, Service Campaign or Service Action repairs should be completed. If you have any questions concerning this recall send them to recall@volvocars.com.

C. PARTS / PARTS RETURN

Please refer to Parts Bulletin R29936. No parts are required to be returned for this recall.

PORT VEHICLES

All vehicles must be checked for any incomplete recalls or service campaigns or service upgrades prior to delivery.

D. OWNER NOTIFICATION

The owner notification letters are scheduled to be mailed in June.

E. VEHICLES IN RETAILER INVENTORY

It is a violation of federal law for a retailer to deliver any new Volvo that is eligible for a recall. Retailers are advised to check all vehicles in inventory for recall eligibility and repair immediately. Violation of this requirement by a retailer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

F. RETAILER RESPONSIBILITY

All vehicles qualifying for this recall must be repaired prior to a customer taking possession of the vehicle.

G. CAMPAIGN REIMBURSEMENT PROCEDURES

Recall R29936 claims should be submitted using the LONG FORM application only.

H. TECHNICIAN COMPETENCY REQUIREMENT

The technician competency requirement for this campaign repair is: Level 3 - Master Tech.



I. RETAILER ALLOWANCE (LONG FORM APPLICATION)

Claim Type:	R29936
Cause Code:	02
CSC Code:	XW
Main OP:	97544
Failed Part:	32252299, 32138231

Repair Description	<u>Oty</u>	<u>Engine</u>	<u>Labor Time</u>
Replace Coolant Bleeder Hose	1	B4204T23 (T5)	0.8
		B4204T27 (T6)	2.4
		B4204T28 (T8)	2.9
			Replace Coolant Bleeder Hose1B4204T23 (T5)B4204T27 (T6)