

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5194
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 16, 2019

Subject: N182206310-02 – Safety Recall
Diesel Engine Block Heater Cord
Revised Service Procedure

Models: 2017 – 2019 Chevrolet Silverado 2500/3500
2017 – 2019 GMC Sierra 2500/3500
Equipped with 6.6L, 8-cylinder diesel engine (RPO L5P)

To: All General Motors Dealers

This bulletin is being revised to add the disabling procedure for inventory vehicles in warm weather states*. The warm weather states* do not have parts available and will need to perform the disabling procedure on inventory units.

*Alabama, Arizona, Arkansas, California, Connecticut, Delaware, Florida, Georgia, Hawaii, Illinois, Indiana, Iowa, Kansas, Kentucky, Louisiana, Maryland, Massachusetts, Missouri, Nebraska, Nevada, New Jersey, New Mexico, Ohio, Oklahoma, Oregon, Pennsylvania, Rhode Island, South Carolina, Tennessee, Texas, Utah, Virginia, Washington, and West Virginia

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS