

Attn: Indian Motorcycle Dealers

Subject: Safety Bulletin I-19-02 Released

Key Actions & Timing: Please Read

Questions: Contact Indian Motorcycle Technical Service

Dear Indian Motorcycle Dealer,

Indian Motorcycle has decided that an electrical defect may exist in 2014 Indian Motorcycles (111 c.i.), resulting in the unexpected loss of forward lighting. This defect may also cause thermal damage to the Vehicle Control Module (VCM) and Pin 11 of the center VCM connector.

- Click [HERE](#) to view I-19-02
- Click [HERE](#) to view I-19-02 Dealer FAQs

Thank you for your attention.

Sincerely,

Indian Motorcycle Service