

# SAFETY RECALL N335 - DOOR MAY NOT LATCH - TECHNICAL BULLETIN PROCEDURES



NAS19.11.003 | WORKSHOP  
ISSUE 2

USA

AFTERSALES BULLETIN  
NOVEMBER 13, 2019

## **NOTE - this bulletin updates/supersedes all previous versions.**

Technical Bulletin N335NAS1, *SAFETY RECALL: Door May Not Latch*, contains two Diagnostic Procedures (A and B) and one Workshop Procedure.

In response to retailer questions, please be advised that **all** affected vehicles require both an IDU2 test (Diagnostic Procedure A) to check door latch operation **and** a software update (Diagnostic Procedure B) to disable the Fast Unlock/Open actuator. It is also essential that Diagnostic Procedure A, the IDU2 test, is completed **before** completing Diagnostic Procedure B, the software update.

The Workshop Procedure to rework door latches is only for vehicles which fail the IDU2 test in Diagnostic Procedure A.

Also make sure all SDD diagnostic tools used for this recall repair are updated with the latest version of software, currently this is 158.04, software management pack 329.

Please ensure this information is shared with all technicians and that all applicable procedures in the Technical Bulletin N335NAS1 are completed when performing a repair to these vehicles under this program.

---

For questions regarding the content of this publication, please contact:

Alan Clarke                      Critical Concerns Engineer  
201.818.8373                      aclark43@jaguarlandrover.com

Jaguar Land Rover North America, LLC  
100 Jaguar Land Rover Way  
Mahwah, NJ 07495